

EMBROIDERY

Stitch Count Estimator

To use the stitch estimator below, photocopy your artwork to fit within the box below. Hat artwork should be no taller than 2" and left chest artwork is no wider than 3-1/2". Count how many 1/4" boxes are covered by your image. Find the corresponding number in the first column. Use column 2 for number of inches covered.

Keep in mind this is a "rough" estimate and digitizers may opt for stitching some of the designs on top of other fields of stitching which will double the stitch count in those areas.

— 1 inch —

# of 1/4"	Stitches	# of 1"	Stitches
1	125	1	2000
2	250	2	4000
3	375	3	6000
4	500	4	8000
5	625	5	10,000
6	750	6	12,000
7	875	7	14,000
8	1000	8	16,000
9	1125	9	18,000
10	1250	10	20,000
11	1375	11	22,000
12	1500	12	24,000
13	1625	13	26,000
14	1750	14	28,000
15	1875	15	30,000